



COARSE

FINE

PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY

<p>MACHINE SCREW NUT, ZINC, COARSE</p> <p>#6  32</p> <p>NUT-HMZ6-32 MN-6-32</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>6 32  1 2</p> <p>MS-6-32RX1/2</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>6 32  3 4</p> <p>MS-6-32RX3/4</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>6 32  1</p> <p>MS-6-32RX1</p>	<p>MACHINE SCREW NUT, ZINC, COARSE</p> <p>#12  24</p> <p>NUT-HMZ12-24 MN-12-24</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>12 24  1</p> <p>MS-12-24RX1</p>
<p>MACHINE SCREW NUT, ZINC, COARSE</p> <p>#8  32</p> <p>NUT-HMZ8-32 MN-8-32</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>8 32  1 2</p> <p>MS-8-32RX1/2</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>8 32  3 4</p> <p>MS-8-32RX3/4</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>8 32  1</p> <p>MS-8-32RX1</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>12 24  3 4</p> <p>MS-12-24RX3/4</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>12 24  1 2</p> <p>MS-12-24RX11/2</p>
<p>MACHINE SCREW NUT, ZINC, COARSE</p> <p>#10  24</p> <p>NUT-HMZ10-24 MN-10-24</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>10 24  1 2</p> <p>MS-10-24RX1/2</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>10 24  3 4</p> <p>MS-10-24RX3/4</p>	<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>10 24  1</p> <p>MS-10-24RX1</p>		<p>SLOTTED MACHINE SCREW, ZINC, COARSE</p> <p>10 24  1 2</p> <p>MS-10-24RX11/2</p>
<p>MACHINE SCREW NUT, ZINC, FINE</p> <p>#10  32</p> <p>NUT-HMZ10-32 MN-10-32</p>	<p>SLOTTED MACHINE SCREW, ZINC, FINE</p> <p>10 32  1 2</p> <p>MS-10-32RX1/2</p>	<p>SLOTTED MACHINE SCREW, ZINC, FINE</p> <p>10 32  3 4</p> <p>MS-10-32RX3/4</p>	<p>SLOTTED MACHINE SCREW, ZINC, FINE</p> <p>10 32  1</p> <p>MS-10-32RX1</p>		<p>SLOTTED MACHINE SCREW, ZINC, FINE</p> <p>10 32  1 2</p> <p>MS-10-32RX11/2</p>