



COARSE

FINE

PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY

<p>MACHINE SCREW NUT, ZINC, COARSE</p> <p><b>#6</b> <b>32</b></p> <p>NUT-HMZ6-32 MN-6-32</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>6</b> <b>1 1/2</b></p> <p>MS-6-32PFX1/2</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>6</b> <b>3 1/4</b></p> <p>MS-6-32PFX3/4</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>6</b> <b>1</b></p> <p>MS-6-32PFX1</p>	<p>MACHINE NUT, ZINC, COARSE</p> <p><b>#12</b> <b>24</b></p> <p>NUT-HMZ12-24 MN-12-24</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>12</b> <b>1</b></p> <p>MS-12-24PFX1</p>
<p>MACHINE SCREW NUT, ZINC, COARSE</p> <p><b>#8</b> <b>32</b></p> <p>NUT-HMZ8-32 MN-8-32</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>8</b> <b>1 1/2</b></p> <p>MS-8-32PFX1/2</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>8</b> <b>3 1/4</b></p> <p>MS-8-32PFX3/4</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>8</b> <b>1</b></p> <p>MS-8-32PFX1</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>12</b> <b>3 1/4</b></p> <p>MS-12-24PFX3/4</p>	
<p>MACHINE SCREW NUT, ZINC, COARSE</p> <p><b>#10</b> <b>24</b></p> <p>NUT-HMZ10-24 MN-10-24</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>10</b> <b>1 1/2</b></p> <p>MS-10-24PFX1/2</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>10</b> <b>3 1/4</b></p> <p>MS-10-24PFX3/4</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>10</b> <b>1</b></p> <p>MS-10-24PFX1</p>		<p>PHILLIPS FLAT MACHINE SCREW, ZINC, COARSE</p> <p><b>10</b> <b>1 1/2</b></p> <p>MS-10-24PFX11/2</p>
<p>MACHINE SCREW NUT, ZINC, FINE</p> <p><b>#10</b> <b>32</b></p> <p>NUT-HMZ10-32 MN-10-32</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, FINE</p> <p><b>10</b> <b>1 1/2</b></p> <p>MS-10-32PFX1/2</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, FINE</p> <p><b>10</b> <b>3 1/4</b></p> <p>MS-10-32PFX3/4</p>	<p>PHILLIPS FLAT MACHINE SCREW, ZINC, FINE</p> <p><b>10</b> <b>1</b></p> <p>MS-10-32PFX1</p>		<p>PHILLIPS FLAT MACHINE SCREW, ZINC, FINE</p> <p><b>10</b> <b>1 1/2</b></p> <p>MS-10-32PFX11/2</p>