











































<p>CAP SCREW</p> <p>$\frac{1}{4}$" C  $\frac{3}{4}$"</p> <p>SOC-1/4CX3/4</p>	<p>CAP SCREW</p> <p>$\frac{1}{4}$" C  1"</p> <p>SOC-1/4CX1</p>	<p>CAP SCREW</p> <p>$\frac{1}{4}$" C  $1\frac{1}{2}$"</p> <p>SOC-1/4CX11/2</p>	<p>CAP SCREW</p> <p>$\frac{1}{4}$" C  2"</p> <p>SOC-1/4CX2</p>	<p>CAP SCREW</p> <p>$\frac{5}{16}$" C  $\frac{3}{4}$"</p> <p>SOC-5/16CX3/4</p>	<p>CAP SCREW</p> <p>$\frac{5}{16}$" C  1"</p> <p>SOC-5/16CX1</p>	<p>CAP SCREW</p> <p>$\frac{5}{16}$" C  $1\frac{1}{2}$"</p> <p>SOC-5/16CX11/2</p>	<p>CAP SCREW</p> <p>$\frac{5}{16}$" C  2"</p> <p>SOC-5/16CX2</p>
<p>CAP SCREW</p> <p>$\frac{3}{8}$" C  $\frac{3}{4}$"</p> <p>SOC-3/8CX3/4</p>	<p>CAP SCREW</p> <p>$\frac{3}{8}$" C  1"</p> <p>SOC-3/8CX1</p>	<p>CAP SCREW</p> <p>$\frac{3}{8}$" C  $1\frac{1}{2}$"</p> <p>SOC-3/8CX11/2</p>	<p>CAP SCREW</p> <p>$\frac{3}{8}$" C  2"</p> <p>SOC-3/8CX2</p>	<p>CAP SCREW</p> <p>$\frac{3}{8}$" C  3"</p> <p>SOC-3/8CX3</p>	<p>CAP SCREW</p> <p>$\frac{1}{2}$" C  1"</p> <p>SOC-1/2CX1</p>	<p>CAP SCREW</p> <p>$\frac{1}{2}$" C  $1\frac{1}{2}$"</p> <p>SOC-1/2CX11/2</p>	<p>CAP SCREW</p> <p>$\frac{1}{2}$" C  2"</p> <p>SOC-1/2CX2</p>
<p>CAP SCREW</p> <p>$\frac{1}{2}$" C  $2\frac{1}{2}$"</p> <p>SOC-1/2CX21/2</p>	<p>CAP SCREW</p> <p>$\frac{1}{2}$" C  3"</p> <p>SOC-1/2CX3</p>	<p>CAP SCREW</p> <p>$\frac{1}{2}$" C  $3\frac{1}{2}$"</p> <p>SOC-1/2CX31/2</p>	<p>CAP SCREW</p> <p>$\frac{1}{2}$" C  4"</p> <p>SOC-1/2CX4</p>	<p>CAP SCREW</p> <p>$\frac{5}{8}$" C  $1\frac{1}{2}$"</p> <p>SOC-5/8CX11/2</p>	<p>CAP SCREW</p> <p>$\frac{5}{8}$" C  2"</p> <p>SOC-5/8CX2</p>	<p>CAP SCREW</p> <p>$\frac{5}{8}$" C  $2\frac{1}{2}$"</p> <p>SOC-5/8CX21/2</p>	<p>CAP SCREW</p> <p>$\frac{5}{8}$" C  3"</p> <p>SOC-5/8CX3</p>
<p>CAP SCREW</p> <p>$\frac{5}{8}$" C  $3\frac{1}{2}$"</p> <p>SOC-5/8CX31/2</p>	<p>CAP SCREW</p> <p>$\frac{5}{8}$" C  4"</p> <p>SOC-5/8CX4</p>	<p>CAP SCREW</p> <p>$\frac{3}{4}$" C  2"</p> <p>SOC-3/4CX2</p>	<p>CAP SCREW</p> <p>$\frac{3}{4}$" C  $2\frac{1}{2}$"</p> <p>SOC-3/4CX21/2</p>	<p>CAP SCREW</p> <p>$\frac{3}{4}$" C  3"</p> <p>SOC-3/4CX3</p>	<p>CAP SCREW</p> <p>$\frac{3}{4}$" C  $3\frac{1}{2}$"</p> <p>SOC-3/4CX31/2</p>	<p>CAP SCREW</p> <p>$\frac{3}{4}$" C  4"</p> <p>SOC-3/4CX4</p>	<p>CAP SCREW</p> <p>$\frac{7}{8}$" C  2"</p> <p>SOC-7/8CX2</p>
<p>CAP SCREW</p> <p>$\frac{7}{8}$" C  $2\frac{1}{2}$"</p> <p>SOC-7/8CX21/2</p>	<p>CAP SCREW</p> <p>$\frac{7}{8}$" C  3"</p> <p>SOC-7/8CX3</p>	<p>CAP SCREW</p> <p>$\frac{7}{8}$" C  $3\frac{1}{2}$"</p> <p>SOC-7/8CX31/2</p>	<p>CAP SCREW</p> <p>$\frac{7}{8}$" C  4"</p> <p>SOC-7/8CX4</p>	<p>CAP SCREW</p> <p>1" C  $2\frac{1}{2}$"</p> <p>SOC-1CX21/2</p>	<p>CAP SCREW</p> <p>1" C  3"</p> <p>SOC-1CX3</p>	<p>CAP SCREW</p> <p>1" C  $3\frac{1}{2}$"</p> <p>SOC-1CX31/2</p>	<p>CAP SCREW</p> <p>1" C  4"</p> <p>SOC-1CX4</p>

PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY