


## GRADE 8 BOLT, NUT, & WASHER, COARSE (ZINC)

ASST-5900




PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY

HEX NUT 1/4 C PL8-1/4C	LOCK WASHER 1/4 P G8L-1/4P	FLAT WASHER 1/4 P SAE G8F-1/4P-SAE	HEX HEAD CAP SCREW 1/4 C 3/4 PL8-1/4CX3/4	HEX HEAD CAP SCREW 1/4 C 1 PL8-1/4CX1	HEX HEAD CAP SCREW 1/4 C 1 1/4 PL8-1/4CX11/4	HEX HEAD CAP SCREW 1/4 C 1 1/2 PL8-1/4CX11/2	HEX HEAD CAP SCREW 1/4 C 1 3/4 PL8-1/4CX13/4
HEX NUT 5/16 C PL8-5/16C	LOCK WASHER 5/16 P G8L-5/16P	FLAT WASHER 5/16 P SAE G8F-5/16P-SAE	HEX HEAD CAP SCREW 5/16 C 3/4 PL8-5/16CX3/4	HEX HEAD CAP SCREW 5/16 C 1 PL8-5/16CX1	HEX HEAD CAP SCREW 5/16 C 1 1/4 PL8-5/16CX11/4	HEX HEAD CAP SCREW 5/16 C 1 1/2 PL8-5/16CX11/2	HEX HEAD CAP SCREW 5/16 C 1 3/4 PL8-5/16CX13/4
HEX NUT 3/8 C PL8-3/8C	LOCK WASHER 3/8 P G8L-3/8P	FLAT WASHER 3/8 P SAE G8F-3/8P-SAE	HEX HEAD CAP SCREW 3/8 C 3/4 PL8-3/8CX3/4	HEX HEAD CAP SCREW 3/8 C 1 PL8-3/8CX1	HEX HEAD CAP SCREW 3/8 C 1 1/4 PL8-3/8CX11/4	HEX HEAD CAP SCREW 3/8 C 1 1/2 PL8-3/8CX11/2	HEX HEAD CAP SCREW 3/8 C 1 3/4 PL8-3/8CX13/4
HEX NUT 7/16 C PL8-7/16C	LOCK WASHER 7/16 P G8L-7/16P	FLAT WASHER 7/16 P SAE G8F-7/16P-SAE	HEX HEAD CAP SCREW 7/16 C 1 PL8-7/16CX1	HEX HEAD CAP SCREW 7/16 C 1 1/4 PL8-7/16CX11/4	HEX HEAD CAP SCREW 7/16 C 1 1/2 PL8-7/16CX11/2	HEX HEAD CAP SCREW 7/16 C 1 3/4 PL8-7/16CX13/4	HEX HEAD CAP SCREW 7/16 C 2 PL8-7/16CX2
HEX NUT 1/2 C PL8-1/2C	LOCK WASHER 1/2 P G8L-1/2P	FLAT WASHER 1/2 P SAE G8F-1/2P-SAE	HEX HEAD CAP SCREW 1/2 C 1 1/4 PL8-1/2CX11/4	HEX HEAD CAP SCREW 1/2 C 1 1/2 PL8-1/2CX11/2	HEX HEAD CAP SCREW 1/2 C 1 3/4 PL8-1/2CX13/4	HEX HEAD CAP SCREW 1/2 C 2 PL8-1/2CX2	HEX HEAD CAP SCREW 1/2 C 2 1/4 PL8-1/2CX21/4

HEX HEAD CAP SCREW 1/4 C 2 PL8-1/4CX2	HEX HEAD CAP SCREW 1/4 C 2 1/2 PL8-1/4CX21/2	HEX HEAD CAP SCREW 1/4 C 3 PL8-1/4CX3	HEX HEAD CAP SCREW 1/4 C 3 1/2 PL8-1/4CX31/2	HEX HEAD CAP SCREW 1/4 C 4 PL8-1/4CX4	HEX HEAD CAP SCREW 1/4 C 4 1/2 PL8-1/4CX41/2	HEX HEAD CAP SCREW 1/4 C 5 PL8-1/4CX5	HEX HEAD CAP SCREW 1/4 C 6 PL8-1/4CX6
HEX HEAD CAP SCREW 5/16 C 2 PL8-5/16CX2	HEX HEAD CAP SCREW 5/16 C 2 1/2 PL8-5/16CX21/2	HEX HEAD CAP SCREW 5/16 C 3 PL8-5/16CX3	HEX HEAD CAP SCREW 5/16 C 3 1/2 PL8-5/16CX31/2	HEX HEAD CAP SCREW 5/16 C 4 PL8-5/16CX4	HEX HEAD CAP SCREW 5/16 C 4 1/2 PL8-5/16CX41/2	HEX HEAD CAP SCREW 5/16 C 5 PL8-5/16CX5	HEX HEAD CAP SCREW 5/16 C 6 PL8-5/16CX6
HEX HEAD CAP SCREW 3/8 C 2 PL8-3/8CX2	HEX HEAD CAP SCREW 3/8 C 2 1/2 PL8-3/8CX21/2	HEX HEAD CAP SCREW 3/8 C 3 PL8-3/8CX3	HEX HEAD CAP SCREW 3/8 C 3 1/2 PL8-3/8CX31/2	HEX HEAD CAP SCREW 3/8 C 4 PL8-3/8CX4	HEX HEAD CAP SCREW 3/8 C 4 1/2 PL8-3/8CX41/2	HEX HEAD CAP SCREW 3/8 C 5 PL8-3/8CX5	HEX HEAD CAP SCREW 3/8 C 6 PL8-3/8CX6
HEX HEAD CAP SCREW 7/16 C 2 1/2 PL8-7/16CX21/2	HEX HEAD CAP SCREW 7/16 C 3 PL8-7/16CX3	HEX HEAD CAP SCREW 7/16 C 3 1/2 PL8-7/16CX31/2	HEX HEAD CAP SCREW 7/16 C 4 PL8-7/16CX4	HEX HEAD CAP SCREW 7/16 C 5 PL8-7/16CX5	HEX HEAD CAP SCREW 7/16 C 6 PL8-7/16CX6		
HEX HEAD CAP SCREW 1/2 C 2 1/2 PL8-1/2CX21/2	HEX HEAD CAP SCREW 1/2 C 3 PL8-1/2CX3	HEX HEAD CAP SCREW 1/2 C 3 1/2 PL8-1/2CX31/2	HEX HEAD CAP SCREW 1/2 C 4 PL8-1/2CX4	HEX HEAD CAP SCREW 1/2 C 4 1/2 PL8-1/2CX41/2	HEX HEAD CAP SCREW 1/2 C 5 PL8-1/2CX5	HEX HEAD CAP SCREW 1/2 C 5 1/2 PL8-1/2CX51/2	HEX HEAD CAP SCREW 1/2 C 6 PL8-1/2CX6


HEX NUT 9/16 C PL8-9/16C	LOCK WASHER 9/16 P G8L-9/16P	FLAT WASHER 9/16 P SAE G8F-9/16P-SAE	HEX HEAD CAP SCREW 9/16 C 1 1/2 PL8-9/16CX11/2	HEX HEAD CAP SCREW 9/16 C 2 PL8-9/16CX2	HEX HEAD CAP SCREW 9/16 C 2 1/2 PL8-9/16CX21/2	HEX HEAD CAP SCREW 9/16 C 3 PL8-9/16CX3	HEX HEAD CAP SCREW 9/16 C 3 1/2 PL8-9/16CX31/2
HEX NUT 5/8 C PL8-5/8C	LOCK WASHER 5/8 P G8L-5/8P	FLAT WASHER 5/8 P SAE G8F-5/8P-SAE	HEX HEAD CAP SCREW 5/8 C 1 1/4 PL8-5/8CX11/4	HEX HEAD CAP SCREW 5/8 C 1 1/2 PL8-5/8CX11/2	HEX HEAD CAP SCREW 5/8 C 1 3/4 PL8-5/8CX13/4	HEX HEAD CAP SCREW 5/8 C 2 PL8-5/8CX2	HEX HEAD CAP SCREW 5/8 C 2 1/4 PL8-5/8CX21/4
HEX NUT 3/4 C PL8-3/4C	LOCK WASHER 3/4 P G8L-3/4P	FLAT WASHER 3/4 P SAE G8F-3/4P-SAE	HEX HEAD CAP SCREW 3/4 C 1 1/2 PL8-3/4CX11/2	HEX HEAD CAP SCREW 3/4 C 1 3/4 PL8-3/4CX13/4	HEX HEAD CAP SCREW 3/4 C 2 PL8-3/4CX2	HEX HEAD CAP SCREW 3/4 C 2 1/2 PL8-3/4CX21/2	HEX HEAD CAP SCREW 3/4 C 3 PL8-3/4CX3
HEX NUT 7/8 C PL8-7/8C	LOCK WASHER 7/8 P G8L-7/8P	FLAT WASHER 7/8 P SAE G8F-7/8P-SAE	HEX HEAD CAP SCREW 7/8 C 2 PL8-7/8CX2	HEX HEAD CAP SCREW 7/8 C 2 1/2 PL8-7/8CX21/2	HEX HEAD CAP SCREW 7/8 C 3 PL8-7/8CX3	HEX HEAD CAP SCREW 7/8 C 3 1/2 PL8-7/8CX31/2	HEX HEAD CAP SCREW 7/8 C 4 PL8-7/8CX4
HEX NUT 1 C PL8-1C	LOCK WASHER 1 P G8L-1P	FLAT WASHER 1 P SAE G8F-1P-SAE	HEX HEAD CAP SCREW 1 C 2 PL8-1CX2	HEX HEAD CAP SCREW 1 C 2 1/2 PL8-1CX21/2	HEX HEAD CAP SCREW 1 C 3 PL8-1CX3	HEX HEAD CAP SCREW 1 C 3 1/2 PL8-1CX31/2	HEX HEAD CAP SCREW 1 C 4 PL8-1CX4

HEX HEAD CAP SCREW 9/16 C 4 PL8-9/16CX4							
HEX HEAD CAP SCREW 5/8 C 2 1/2 PL8-5/8CX21/2	HEX HEAD CAP SCREW 5/8 C 3 PL8-5/8CX3	HEX HEAD CAP SCREW 5/8 C 3 1/2 PL8-5/8CX31/2	HEX HEAD CAP SCREW 5/8 C 4 PL8-5/8CX4	HEX HEAD CAP SCREW 5/8 C 4 1/2 PL8-5/8CX41/2	HEX HEAD CAP SCREW 5/8 C 5 PL8-5/8CX5	HEX HEAD CAP SCREW 5/8 C 5 1/2 PL8-5/8CX51/2	HEX HEAD CAP SCREW 5/8 C 6 PL8-5/8CX6
HEX HEAD CAP SCREW 3/4 C 3 1/2 PL8-3/4CX31/2	HEX HEAD CAP SCREW 3/4 C 4 PL8-3/4CX4	HEX HEAD CAP SCREW 3/4 C 4 1/2 PL8-3/4CX41/2	HEX HEAD CAP SCREW 3/4 C 5 PL8-3/4CX5	HEX HEAD CAP SCREW 3/4 C 5 1/2 PL8-3/4CX51/2	HEX HEAD CAP SCREW 3/4 C 6 PL8-3/4CX6		
HEX HEAD CAP SCREW 7/8 C 4 1/2 PL8-7/8CX41/2	HEX HEAD CAP SCREW 7/8 C 5 PL8-7/8CX5	HEX HEAD CAP SCREW 7/8 C 5 1/2 PL8-7/8CX51/2	HEX HEAD CAP SCREW 7/8 C 6 PL8-7/8CX6				
HEX HEAD CAP SCREW 1 C 4 1/2 PL8-1CX41/2	HEX HEAD CAP SCREW 1 C 5 PL8-1CX5	HEX HEAD CAP SCREW 1 C 5 1/2 PL8-1CX51/2	HEX HEAD CAP SCREW 1 C 6 PL8-1CX6				




<p>HEX NUT</p> <p><math>\frac{1}{4}</math>C </p> <p>PL8-1/4C</p>	<p>LOCK WASHER</p> <p><math>\frac{1}{4}</math>P </p> <p>G8L-1/4P</p>	<p>FLAT WASHER</p> <p><math>\frac{1}{4}</math>P  SAE</p> <p>G8F-1/4P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>C  <math>\frac{3}{4}</math></p> <p>PL8-1/4CX3/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>C  1</p> <p>PL8-1/4CX1</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>C  <math>1\frac{1}{4}</math></p> <p>PL8-1/4CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>C  <math>1\frac{1}{2}</math></p> <p>PL8-1/4CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>C  <math>1\frac{3}{4}</math></p> <p>PL8-1/4CX13/4</p>
<p>HEX NUT</p> <p><math>\frac{5}{16}</math>C </p> <p>PL8-5/16C</p>	<p>LOCK WASHER</p> <p><math>\frac{5}{16}</math>P </p> <p>G8L-5/16P</p>	<p>FLAT WASHER</p> <p><math>\frac{5}{16}</math>P  SAE</p> <p>G8F-5/16P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>C  <math>\frac{3}{4}</math></p> <p>PL8-5/16CX3/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>C  1</p> <p>PL8-5/16CX1</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>C  <math>1\frac{1}{4}</math></p> <p>PL8-5/16CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>C  <math>1\frac{1}{2}</math></p> <p>PL8-5/16CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>C  <math>1\frac{3}{4}</math></p> <p>PL8-5/16CX13/4</p>
<p>HEX NUT</p> <p><math>\frac{3}{8}</math>C </p> <p>PL8-3/8C</p>	<p>LOCK WASHER</p> <p><math>\frac{3}{8}</math>P </p> <p>G8L-3/8P</p>	<p>FLAT WASHER</p> <p><math>\frac{3}{8}</math>P  SAE</p> <p>G8F-3/8P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>C  <math>\frac{3}{4}</math></p> <p>PL8-3/8CX3/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>C  1</p> <p>PL8-3/8CX1</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>C  <math>1\frac{1}{4}</math></p> <p>PL8-3/8CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>C  <math>1\frac{1}{2}</math></p> <p>PL8-3/8CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>C  <math>1\frac{3}{4}</math></p> <p>PL8-3/8CX13/4</p>
<p>HEX NUT</p> <p><math>\frac{7}{16}</math>C </p> <p>PL8-7/16C</p>	<p>LOCK WASHER</p> <p><math>\frac{7}{16}</math>P </p> <p>G8L-7/16P</p>	<p>FLAT WASHER</p> <p><math>\frac{7}{16}</math>P  SAE</p> <p>G8F-7/16P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>C  1</p> <p>PL8-7/16CX1</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>C  <math>1\frac{1}{4}</math></p> <p>PL8-7/16CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>C  <math>1\frac{1}{2}</math></p> <p>PL8-7/16CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>C  <math>1\frac{3}{4}</math></p> <p>PL8-7/16CX13/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>C  2</p> <p>PL8-7/16CX2</p>
<p>HEX NUT</p> <p><math>\frac{1}{2}</math>C </p> <p>PL8-1/2C</p>	<p>LOCK WASHER</p> <p><math>\frac{1}{2}</math>P </p> <p>G8L-1/2P</p>	<p>FLAT WASHER</p> <p><math>\frac{1}{2}</math>P  SAE</p> <p>G8F-1/2P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>C  <math>1\frac{1}{4}</math></p> <p>PL8-1/2CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>C  <math>1\frac{1}{2}</math></p> <p>PL8-1/2CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>C  <math>1\frac{3}{4}</math></p> <p>PL8-1/2CX13/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>C  2</p> <p>PL8-1/2CX2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>C  <math>2\frac{1}{4}</math></p> <p>PL8-1/2CX21/4</p>









































PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY



























<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>" C 2</p> <p>PL8-1/4CX2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>" C 2 1/2</p> <p>PL8-1/4CX2 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>" C 3</p> <p>PL8-1/4CX3</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>" C 3 1/2</p> <p>PL8-1/4CX3 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>" C 4</p> <p>PL8-1/4CX4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>" C 4 1/2</p> <p>PL8-1/4CX4 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>" C 5</p> <p>PL8-1/4CX5</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{4}</math>" C 6</p> <p>PL8-1/4CX6</p>
<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>" C 2</p> <p>PL8-5/16CX2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>" C 2 1/2</p> <p>PL8-5/16CX2 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>" C 3</p> <p>PL8-5/16CX3</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>" C 3 1/2</p> <p>PL8-5/16CX3 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>" C 4</p> <p>PL8-5/16CX4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>" C 4 1/2</p> <p>PL8-5/16CX4 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>" C 5</p> <p>PL8-5/16CX5</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{16}</math>" C 6</p> <p>PL8-5/16CX6</p>
<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>" C 2</p> <p>PL8-3/8CX2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>" C 2 1/2</p> <p>PL8-3/8CX2 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>" C 3</p> <p>PL8-3/8CX3</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>" C 3 1/2</p> <p>PL8-3/8CX3 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>" C 4</p> <p>PL8-3/8CX4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>" C 4 1/2</p> <p>PL8-3/8CX4 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>" C 5</p> <p>PL8-3/8CX5</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{8}</math>" C 6</p> <p>PL8-3/8CX6</p>
<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>" C 2 1/2</p> <p>PL8-7/16CX2 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>" C 3</p> <p>PL8-7/16CX3</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>" C 3 1/2</p> <p>PL8-7/16CX3 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>" C 4</p> <p>PL8-7/16CX4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>" C 5</p> <p>PL8-7/16CX5</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{16}</math>" C 6</p> <p>PL8-7/16CX6</p>		
<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>" C 2 1/2</p> <p>PL8-1/2CX2 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>" C 3</p> <p>PL8-1/2CX3</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>" C 3 1/2</p> <p>PL8-1/2CX3 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>" C 4</p> <p>PL8-1/2CX4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>" C 4 1/2</p> <p>PL8-1/2CX4 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>" C 5</p> <p>PL8-1/2CX5</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>" C 5 1/2</p> <p>PL8-1/2CX5 1/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{1}{2}</math>" C 6</p> <p>PL8-1/2CX6</p>





<p>HEX NUT</p> <p><math>\frac{9}{16}C</math> </p> <p>PL8-9/16C</p>	<p>LOCK WASHER</p> <p><math>\frac{9}{16}</math> </p> <p>G8L-9/16P</p>	<p>FLAT WASHER</p> <p><math>\frac{9}{16}</math>  SAE</p> <p>G8F-9/16P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{9}{16}C</math>  <math>1\frac{1}{2}</math></p> <p>PL8-9/16CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{9}{16}C</math>  2</p> <p>PL8-9/16CX2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{9}{16}C</math>  <math>2\frac{1}{2}</math></p> <p>PL8-9/16CX21/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{9}{16}C</math>  3</p> <p>PL8-9/16CX3</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{9}{16}C</math>  <math>3\frac{1}{2}</math></p> <p>PL8-9/16CX31/2</p>
<p>HEX NUT</p> <p><math>\frac{5}{8}C</math> </p> <p>PL8-5/8C</p>	<p>LOCK WASHER</p> <p><math>\frac{5}{8}</math> </p> <p>G8L-5/8P</p>	<p>FLAT WASHER</p> <p><math>\frac{5}{8}</math>  SAE</p> <p>G8F-5/8P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{8}C</math>  <math>1\frac{1}{4}</math></p> <p>PL8-5/8CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{8}C</math>  <math>1\frac{1}{2}</math></p> <p>PL8-5/8CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{8}C</math>  <math>1\frac{3}{4}</math></p> <p>PL8-5/8CX13/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{8}C</math>  2</p> <p>PL8-5/8CX2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{5}{8}C</math>  <math>2\frac{1}{4}</math></p> <p>PL8-5/8CX21/4</p>
<p>HEX NUT</p> <p><math>\frac{3}{4}C</math> </p> <p>PL8-3/4C</p>	<p>LOCK WASHER</p> <p><math>\frac{3}{4}</math> </p> <p>G8L-3/4P</p>	<p>FLAT WASHER</p> <p><math>\frac{3}{4}</math>  SAE</p> <p>G8F-3/4P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{4}C</math>  <math>1\frac{1}{2}</math></p> <p>PL8-3/4CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{4}C</math>  <math>1\frac{3}{4}</math></p> <p>PL8-3/4CX13/4</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{4}C</math>  2</p> <p>PL8-3/4CX2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{4}C</math>  <math>2\frac{1}{2}</math></p> <p>PL8-3/4CX21/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{3}{4}C</math>  3</p> <p>PL8-3/4CX3</p>
<p>HEX NUT</p> <p><math>\frac{7}{8}C</math> </p> <p>PL8-7/8C</p>	<p>LOCK WASHER</p> <p><math>\frac{7}{8}</math> </p> <p>G8L-7/8P</p>	<p>FLAT WASHER</p> <p><math>\frac{7}{8}</math>  SAE</p> <p>G8F-7/8P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{8}C</math>  2</p> <p>PL8-7/8CX2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{8}C</math>  <math>2\frac{1}{2}</math></p> <p>PL8-7/8CX21/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{8}C</math>  3</p> <p>PL8-7/8CX3</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{8}C</math>  <math>3\frac{1}{2}</math></p> <p>PL8-7/8CX31/2</p>	<p>HEX HEAD CAP SCREW</p> <p><math>\frac{7}{8}C</math>  4</p> <p>PL8-7/8CX4</p>
<p>HEX NUT</p> <p>1C </p> <p>PL8-1C</p>	<p>LOCK WASHER</p> <p>1 </p> <p>G8L-1P</p>	<p>FLAT WASHER</p> <p>1  SAE</p> <p>G8F-1P-SAE</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  2</p> <p>PL8-1CX2</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  <math>2\frac{1}{2}</math></p> <p>PL8-1CX21/2</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  3</p> <p>PL8-1CX3</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  <math>3\frac{1}{2}</math></p> <p>PL8-1CX31/2</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  4</p> <p>PL8-1CX4</p>



HEX HEAD CAP SCREW $\frac{9}{16}$ C 4  PL8-9/16CX4							
HEX HEAD CAP SCREW $\frac{5}{8}$ C $2\frac{1}{2}$  PL8-5/8CX2 1/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C 3  PL8-5/8CX3	HEX HEAD CAP SCREW $\frac{5}{8}$ C $3\frac{1}{2}$  PL8-5/8CX3 1/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C 4  PL8-5/8CX4	HEX HEAD CAP SCREW $\frac{5}{8}$ C $4\frac{1}{2}$  PL8-5/8CX4 1/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C 5  PL8-5/8CX5	HEX HEAD CAP SCREW $\frac{5}{8}$ C $5\frac{1}{2}$  PL8-5/8CX5 1/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C 6  PL8-5/8CX6
HEX HEAD CAP SCREW $\frac{3}{4}$ C $3\frac{1}{2}$  PL8-3/4CX3 1/2	HEX HEAD CAP SCREW $\frac{3}{4}$ C 4  PL8-3/4CX4	HEX HEAD CAP SCREW $\frac{3}{4}$ C $4\frac{1}{2}$  PL8-3/4CX4 1/2	HEX HEAD CAP SCREW $\frac{3}{4}$ C 5  PL8-3/4CX5	HEX HEAD CAP SCREW $\frac{3}{4}$ C $5\frac{1}{2}$  PL8-3/4CX5 1/2	HEX HEAD CAP SCREW $\frac{3}{4}$ C 6  PL8-3/4CX6		
HEX HEAD CAP SCREW $\frac{7}{8}$ C $4\frac{1}{2}$  PL8-7/8CX4 1/2	HEX HEAD CAP SCREW $\frac{7}{8}$ C 5  PL8-7/8CX5	HEX HEAD CAP SCREW $\frac{7}{8}$ C $5\frac{1}{2}$  PL8-7/8CX5 1/2	HEX HEAD CAP SCREW $\frac{7}{8}$ C 6  PL8-7/8CX6				
HEX HEAD CAP SCREW 1C $4\frac{1}{2}$  PL8-1CX4 1/2	HEX HEAD CAP SCREW 1C 5  PL8-1CX5	HEX HEAD CAP SCREW 1C $5\frac{1}{2}$  PL8-1CX5 1/2	HEX HEAD CAP SCREW 1C 6  PL8-1CX6				

PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY