


GRADE 5 BOLT, NUT, & WASHER, COARSE (ZINC) ASST-6000




PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY









































HEX NUT $\frac{1}{4}$ C PL5-1/4C	LOCK WASHER $\frac{1}{4}$ LW-1/4P	FLAT WASHER $\frac{1}{4}$ SAE FW-1/4P-SAE-PC	HEX HEAD CAP SCREW $\frac{1}{4}$ C $\frac{3}{4}$ PL5-1/4CX3/4	HEX HEAD CAP SCREW $\frac{1}{4}$ C 1 PL5-1/4CX1	HEX HEAD CAP SCREW $\frac{1}{4}$ C $1\frac{1}{4}$ PL5-1/4CX11/4	HEX HEAD CAP SCREW $\frac{1}{4}$ C $1\frac{1}{2}$ PL5-1/4CX11/2	HEX HEAD CAP SCREW $\frac{1}{4}$ C $1\frac{3}{4}$ PL5-1/4CX13/4
HEX NUT $\frac{5}{16}$ C PL5-5/16C	LOCK WASHER $\frac{5}{16}$ LW-5/16P	FLAT WASHER $\frac{5}{16}$ SAE FW-5/16P-SAE-PC	HEX HEAD CAP SCREW $\frac{5}{16}$ C $\frac{3}{4}$ PL5-5/16CX3/4	HEX HEAD CAP SCREW $\frac{5}{16}$ C 1 PL5-5/16CX1	HEX HEAD CAP SCREW $\frac{5}{16}$ C $1\frac{1}{4}$ PL5-5/16CX11/4	HEX HEAD CAP SCREW $\frac{5}{16}$ C $1\frac{1}{2}$ PL5-5/16CX11/2	HEX HEAD CAP SCREW $\frac{5}{16}$ C $1\frac{3}{4}$ PL5-5/16CX13/4
HEX NUT $\frac{3}{8}$ C PL5-3/8C	LOCK WASHER $\frac{3}{8}$ LW-3/8P	FLAT WASHER $\frac{3}{8}$ SAE FW-3/8P-SAE-PC	HEX HEAD CAP SCREW $\frac{3}{8}$ C $\frac{3}{4}$ PL5-3/8CX3/4	HEX HEAD CAP SCREW $\frac{3}{8}$ C 1 PL5-3/8CX1	HEX HEAD CAP SCREW $\frac{3}{8}$ C $1\frac{1}{4}$ PL5-3/8CX11/4	HEX HEAD CAP SCREW $\frac{3}{8}$ C $1\frac{1}{2}$ PL5-3/8CX11/2	HEX HEAD CAP SCREW $\frac{3}{8}$ C $1\frac{3}{4}$ PL5-3/8CX13/4
HEX NUT $\frac{7}{16}$ C PL5-7/16C	LOCK WASHER $\frac{7}{16}$ LW-7/16P	FLAT WASHER $\frac{7}{16}$ SAE FW-7/16P-SAE-PC	HEX HEAD CAP SCREW $\frac{7}{16}$ C 1 PL5-7/16CX1	HEX HEAD CAP SCREW $\frac{7}{16}$ C $1\frac{1}{4}$ PL5-7/16CX11/4	HEX HEAD CAP SCREW $\frac{7}{16}$ C $1\frac{1}{2}$ PL5-7/16CX11/2	HEX HEAD CAP SCREW $\frac{7}{16}$ C $1\frac{3}{4}$ PL5-7/16CX13/4	HEX HEAD CAP SCREW $\frac{7}{16}$ C 2 PL5-7/16CX2
HEX NUT $\frac{1}{2}$ C PL5-1/2C	LOCK WASHER $\frac{1}{2}$ LW-1/2P	FLAT WASHER $\frac{1}{2}$ SAE FW-1/2P-SAE-PC	HEX HEAD CAP SCREW $\frac{1}{2}$ C $1\frac{1}{4}$ PL5-1/2CX11/4	HEX HEAD CAP SCREW $\frac{1}{2}$ C $1\frac{1}{2}$ PL5-1/2CX11/2	HEX HEAD CAP SCREW $\frac{1}{2}$ C $1\frac{3}{4}$ PL5-1/2CX13/4	HEX HEAD CAP SCREW $\frac{1}{2}$ C 2 PL5-1/2CX2	HEX HEAD CAP SCREW $\frac{1}{2}$ C $2\frac{1}{4}$ PL5-1/2CX21/4


HEX HEAD CAP SCREW $\frac{1}{4}$ C 2 PL5-1/4CX2	HEX HEAD CAP SCREW $\frac{1}{4}$ C $2\frac{1}{2}$ PL5-1/4CX21/2	HEX HEAD CAP SCREW $\frac{1}{4}$ C 3 PL5-1/4CX3	HEX HEAD CAP SCREW $\frac{1}{4}$ C $3\frac{1}{2}$ PL5-1/4CX31/2	HEX HEAD CAP SCREW $\frac{1}{4}$ C 4 PL5-1/4CX4	HEX HEAD CAP SCREW $\frac{1}{4}$ C $4\frac{1}{2}$ PL5-1/4CX41/2	HEX HEAD CAP SCREW $\frac{1}{4}$ C 5 PL5-1/4CX5	HEX HEAD CAP SCREW $\frac{1}{4}$ C 6 PL5-1/4CX6
HEX HEAD CAP SCREW $\frac{5}{16}$ C 2 PL5-5/16CX2	HEX HEAD CAP SCREW $\frac{5}{16}$ C $2\frac{1}{2}$ PL5-5/16CX21/2	HEX HEAD CAP SCREW $\frac{5}{16}$ C 3 PL5-5/16CX3	HEX HEAD CAP SCREW $\frac{5}{16}$ C $3\frac{1}{2}$ PL5-5/16CX31/2	HEX HEAD CAP SCREW $\frac{5}{16}$ C 4 PL5-5/16CX4	HEX HEAD CAP SCREW $\frac{5}{16}$ C $4\frac{1}{2}$ PL5-5/16CX41/2	HEX HEAD CAP SCREW $\frac{5}{16}$ C 5 PL5-5/16CX5	HEX HEAD CAP SCREW $\frac{5}{16}$ C 6 PL5-5/16CX6
HEX HEAD CAP SCREW $\frac{3}{8}$ C 2 PL5-3/8CX2	HEX HEAD CAP SCREW $\frac{3}{8}$ C $2\frac{1}{2}$ PL5-3/8CX21/2	HEX HEAD CAP SCREW $\frac{3}{8}$ C 3 PL5-3/8CX3	HEX HEAD CAP SCREW $\frac{3}{8}$ C $3\frac{1}{2}$ PL5-3/8CX31/2	HEX HEAD CAP SCREW $\frac{3}{8}$ C 4 PL5-3/8CX4	HEX HEAD CAP SCREW $\frac{3}{8}$ C $4\frac{1}{2}$ PL5-3/8CX41/2	HEX HEAD CAP SCREW $\frac{3}{8}$ C 5 PL5-3/8CX5	HEX HEAD CAP SCREW $\frac{3}{8}$ C 6 PL5-3/8CX6
HEX HEAD CAP SCREW $\frac{7}{16}$ C $2\frac{1}{2}$ PL5-7/16CX21/2	HEX HEAD CAP SCREW $\frac{7}{16}$ C 3 PL5-7/16CX3	HEX HEAD CAP SCREW $\frac{7}{16}$ C $3\frac{1}{2}$ PL5-7/16CX31/2	HEX HEAD CAP SCREW $\frac{7}{16}$ C 4 PL5-7/16CX4	HEX HEAD CAP SCREW $\frac{7}{16}$ C 5 PL5-7/16CX5	HEX HEAD CAP SCREW $\frac{7}{16}$ C 6 PL5-7/16CX6		
HEX HEAD CAP SCREW $\frac{1}{2}$ C $2\frac{1}{2}$ PL5-1/2CX21/2	HEX HEAD CAP SCREW $\frac{1}{2}$ C 3 PL5-1/2CX3	HEX HEAD CAP SCREW $\frac{1}{2}$ C $3\frac{1}{2}$ PL5-1/2CX31/2	HEX HEAD CAP SCREW $\frac{1}{2}$ C 4 PL5-1/2CX4	HEX HEAD CAP SCREW $\frac{1}{2}$ C $4\frac{1}{2}$ PL5-1/2CX41/2	HEX HEAD CAP SCREW $\frac{1}{2}$ C 5 PL5-1/2CX5	HEX HEAD CAP SCREW $\frac{1}{2}$ C $5\frac{1}{2}$ PL5-1/2CX51/2	HEX HEAD CAP SCREW $\frac{1}{2}$ C 6 PL5-1/2CX6

HEX NUT $\frac{9}{16}$ C PL5-9/16C	LOCK WASHER $\frac{9}{16}$ LW-9/16P	FLAT WASHER $\frac{9}{16}$ SAE FW-9/16P-SAE-PC	HEX HEAD CAP SCREW $\frac{9}{16}$ C $1\frac{1}{2}$ PL5-9/16CX11/2	HEX HEAD CAP SCREW $\frac{9}{16}$ C 2 PL5-9/16CX2	HEX HEAD CAP SCREW $\frac{9}{16}$ C $2\frac{1}{2}$ PL5-9/16CX21/2	HEX HEAD CAP SCREW $\frac{9}{16}$ C 3 PL5-9/16CX3	HEX HEAD CAP SCREW $\frac{9}{16}$ C $3\frac{1}{2}$ PL5-9/16CX31/2
HEX NUT $\frac{5}{8}$ C PL5-5/8C	LOCK WASHER $\frac{5}{8}$ LW-5/8P	FLAT WASHER $\frac{5}{8}$ SAE FW-5/8P-SAE-PC	HEX HEAD CAP SCREW $\frac{5}{8}$ C $1\frac{1}{4}$ PL5-5/8CX11/4	HEX HEAD CAP SCREW $\frac{5}{8}$ C $1\frac{1}{2}$ PL5-5/8CX11/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C $1\frac{3}{4}$ PL5-5/8CX13/4	HEX HEAD CAP SCREW $\frac{5}{8}$ C 2 PL5-5/8CX2	HEX HEAD CAP SCREW $\frac{5}{8}$ C $2\frac{1}{4}$ PL5-5/8CX21/4
HEX NUT $\frac{3}{4}$ C PL5-3/4C	LOCK WASHER $\frac{3}{4}$ LW-3/4P	FLAT WASHER $\frac{3}{4}$ SAE FW-3/4P-SAE-PC	HEX HEAD CAP SCREW $\frac{3}{4}$ C $1\frac{1}{2}$ PL5-3/4CX11/2	HEX HEAD CAP SCREW $\frac{3}{4}$ C $1\frac{3}{4}$ PL5-3/4CX13/4	HEX HEAD CAP SCREW $\frac{3}{4}$ C 2 PL5-3/4CX2	HEX HEAD CAP SCREW $\frac{3}{4}$ C $2\frac{1}{2}$ PL5-3/4CX21/2	HEX HEAD CAP SCREW $\frac{3}{4}$ C 3 PL5-3/4CX3
HEX NUT $\frac{7}{8}$ C PL5-7/8C	LOCK WASHER $\frac{7}{8}$ LW-7/8P	FLAT WASHER $\frac{7}{8}$ SAE FW-7/8P-SAE-PC	HEX HEAD CAP SCREW $\frac{7}{8}$ C 2 PL5-7/8CX2	HEX HEAD CAP SCREW $\frac{7}{8}$ C $2\frac{1}{2}$ PL5-7/8CX21/2	HEX HEAD CAP SCREW $\frac{7}{8}$ C 3 PL5-7/8CX3	HEX HEAD CAP SCREW $\frac{7}{8}$ C $3\frac{1}{2}$ PL5-7/8CX31/2	HEX HEAD CAP SCREW $\frac{7}{8}$ C 4 PL5-7/8CX4
HEX NUT 1C PL5-1C	LOCK WASHER 1 LW-1P	FLAT WASHER 1 SAE FW-1P-SAE-PC	HEX HEAD CAP SCREW 1C 2 PL5-1CX2	HEX HEAD CAP SCREW 1C $2\frac{1}{2}$ PL5-1CX21/2	HEX HEAD CAP SCREW 1C 3 PL5-1CX3	HEX HEAD CAP SCREW 1C $3\frac{1}{2}$ PL5-1CX31/2	HEX HEAD CAP SCREW 1C 4 PL5-1CX4

HEX HEAD CAP SCREW $\frac{9}{16}$ C 4 PL5-9/16CX4							
HEX HEAD CAP SCREW $\frac{5}{8}$ C $2\frac{1}{2}$ PL5-5/8CX21/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C 3 PL5-5/8CX3	HEX HEAD CAP SCREW $\frac{5}{8}$ C $3\frac{1}{2}$ PL5-5/8CX31/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C 4 PL5-5/8CX4	HEX HEAD CAP SCREW $\frac{5}{8}$ C $4\frac{1}{2}$ PL5-5/8CX41/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C 5 PL5-5/8CX5	HEX HEAD CAP SCREW $\frac{5}{8}$ C $5\frac{1}{2}$ PL5-5/8CX51/2	HEX HEAD CAP SCREW $\frac{5}{8}$ C 6 PL5-5/8CX6
HEX HEAD CAP SCREW $\frac{3}{4}$ C $3\frac{1}{2}$ PL5-3/4CX31/2	HEX HEAD CAP SCREW $\frac{3}{4}$ C 4 PL5-3/4CX4	HEX HEAD CAP SCREW $\frac{3}{4}$ C $4\frac{1}{2}$ PL5-3/4CX41/2	HEX HEAD CAP SCREW $\frac{3}{4}$ C 5 PL5-3/4CX5	HEX HEAD CAP SCREW $\frac{3}{4}$ C $5\frac{1}{2}$ PL5-3/4CX51/2	HEX HEAD CAP SCREW $\frac{3}{4}$ C 6 PL5-3/4CX6		
HEX HEAD CAP SCREW $\frac{7}{8}$ C $4\frac{1}{2}$ PL5-7/8CX41/2	HEX HEAD CAP SCREW $\frac{7}{8}$ C 5 PL5-7/8CX5	HEX HEAD CAP SCREW $\frac{7}{8}$ C $5\frac{1}{2}$ PL5-7/8CX51/2	HEX HEAD CAP SCREW $\frac{7}{8}$ C 6 PL5-7/8CX6				
HEX HEAD CAP SCREW 1C $4\frac{1}{2}$ PL5-1CX41/2	HEX HEAD CAP SCREW 1C 5 PL5-1CX5	HEX HEAD CAP SCREW 1C $5\frac{1}{2}$ PL5-1CX51/2	HEX HEAD CAP SCREW 1C 6 PL5-1CX6				












































<p>HEX NUT</p> <p>$\frac{1}{4}$C </p> <p>PL5-1/4C</p>	<p>LOCK WASHER</p> <p>$\frac{1}{4}$ </p> <p>LW-1/4P</p>	<p>FLAT WASHER</p> <p>$\frac{1}{4}$  SAE</p> <p>FW-1/4P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{4}$C  $\frac{3}{4}$</p> <p>PL5-1/4CX3/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{4}$C  1</p> <p>PL5-1/4CX1</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{4}$C  $1\frac{1}{4}$</p> <p>PL5-1/4CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{4}$C  $1\frac{1}{2}$</p> <p>PL5-1/4CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{4}$C  $1\frac{3}{4}$</p> <p>PL5-1/4CX13/4</p>
<p>HEX NUT</p> <p>$\frac{5}{16}$C </p> <p>PL5-5/16C</p>	<p>LOCK WASHER</p> <p>$\frac{5}{16}$ </p> <p>LW-5/16P</p>	<p>FLAT WASHER</p> <p>$\frac{5}{16}$  SAE</p> <p>FW-5/16P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{16}$C  $\frac{3}{4}$</p> <p>PL5-5/16CX3/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{16}$C  1</p> <p>PL5-5/16CX1</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{16}$C  $1\frac{1}{4}$</p> <p>PL5-5/16CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{16}$C  $1\frac{1}{2}$</p> <p>PL5-5/16CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{16}$C  $1\frac{3}{4}$</p> <p>PL5-5/16CX13/4</p>
<p>HEX NUT</p> <p>$\frac{3}{8}$C </p> <p>PL5-3/8C</p>	<p>LOCK WASHER</p> <p>$\frac{3}{8}$ </p> <p>LW-3/8P</p>	<p>FLAT WASHER</p> <p>$\frac{3}{8}$  SAE</p> <p>FW-3/8P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{8}$C  $\frac{3}{4}$</p> <p>PL5-3/8CX3/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{8}$C  1</p> <p>PL5-3/8CX1</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{8}$C  $1\frac{1}{4}$</p> <p>PL5-3/8CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{8}$C  $1\frac{1}{2}$</p> <p>PL5-3/8CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{8}$C  $1\frac{3}{4}$</p> <p>PL5-3/8CX13/4</p>
<p>HEX NUT</p> <p>$\frac{7}{16}$C </p> <p>PL5-7/16C</p>	<p>LOCK WASHER</p> <p>$\frac{7}{16}$ </p> <p>LW-7/16P</p>	<p>FLAT WASHER</p> <p>$\frac{7}{16}$  SAE</p> <p>FW-7/16P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{16}$C  1</p> <p>PL5-7/16CX1</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{16}$C  $1\frac{1}{4}$</p> <p>PL5-7/16CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{16}$C  $1\frac{1}{2}$</p> <p>PL5-7/16CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{16}$C  $1\frac{3}{4}$</p> <p>PL5-7/16CX13/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{16}$C  2</p> <p>PL5-7/16CX2</p>
<p>HEX NUT</p> <p>$\frac{1}{2}$C </p> <p>PL5-1/2C</p>	<p>LOCK WASHER</p> <p>$\frac{1}{2}$ </p> <p>LW-1/2P</p>	<p>FLAT WASHER</p> <p>$\frac{1}{2}$  SAE</p> <p>FW-1/2P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{2}$C  $1\frac{1}{4}$</p> <p>PL5-1/2CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{2}$C  $1\frac{1}{2}$</p> <p>PL5-1/2CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{2}$C  $1\frac{3}{4}$</p> <p>PL5-1/2CX13/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{2}$C  2</p> <p>PL5-1/2CX2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{1}{2}$C  $2\frac{1}{4}$</p> <p>PL5-1/2CX21/4</p>



























HEX HEAD CAP SCREW $\frac{1}{4}$ " C 2 PL5-1/4CX2	HEX HEAD CAP SCREW $\frac{1}{4}$ " C 2 1/2 PL5-1/4CX2 1/2	HEX HEAD CAP SCREW $\frac{1}{4}$ " C 3 PL5-1/4CX3	HEX HEAD CAP SCREW $\frac{1}{4}$ " C 3 1/2 PL5-1/4CX3 1/2	HEX HEAD CAP SCREW $\frac{1}{4}$ " C 4 PL5-1/4CX4	HEX HEAD CAP SCREW $\frac{1}{4}$ " C 4 1/2 PL5-1/4CX4 1/2	HEX HEAD CAP SCREW $\frac{1}{4}$ " C 5 PL5-1/4CX5	HEX HEAD CAP SCREW $\frac{1}{4}$ " C 6 PL5-1/4CX6
HEX HEAD CAP SCREW $\frac{5}{16}$ " C 2 PL5-5/16CX2	HEX HEAD CAP SCREW $\frac{5}{16}$ " C 2 1/2 PL5-5/16CX2 1/2	HEX HEAD CAP SCREW $\frac{5}{16}$ " C 3 PL5-5/16CX3	HEX HEAD CAP SCREW $\frac{5}{16}$ " C 3 1/2 PL5-5/16CX3 1/2	HEX HEAD CAP SCREW $\frac{5}{16}$ " C 4 PL5-5/16CX4	HEX HEAD CAP SCREW $\frac{5}{16}$ " C 4 1/2 PL5-5/16CX4 1/2	HEX HEAD CAP SCREW $\frac{5}{16}$ " C 5 PL5-5/16CX5	HEX HEAD CAP SCREW $\frac{5}{16}$ " C 6 PL5-5/16CX6
HEX HEAD CAP SCREW $\frac{3}{8}$ " C 2 PL5-3/8CX2	HEX HEAD CAP SCREW $\frac{3}{8}$ " C 2 1/2 PL5-3/8CX2 1/2	HEX HEAD CAP SCREW $\frac{3}{8}$ " C 3 PL5-3/8CX3	HEX HEAD CAP SCREW $\frac{3}{8}$ " C 3 1/2 PL5-3/8CX3 1/2	HEX HEAD CAP SCREW $\frac{3}{8}$ " C 4 PL5-3/8CX4	HEX HEAD CAP SCREW $\frac{3}{8}$ " C 4 1/2 PL5-3/8CX4 1/2	HEX HEAD CAP SCREW $\frac{3}{8}$ " C 5 PL5-3/8CX5	HEX HEAD CAP SCREW $\frac{3}{8}$ " C 6 PL5-3/8CX6
HEX HEAD CAP SCREW $\frac{7}{16}$ " C 2 1/2 PL5-7/16CX2 1/2	HEX HEAD CAP SCREW $\frac{7}{16}$ " C 3 PL5-7/16CX3	HEX HEAD CAP SCREW $\frac{7}{16}$ " C 3 1/2 PL5-7/16CX3 1/2	HEX HEAD CAP SCREW $\frac{7}{16}$ " C 4 PL5-7/16CX4	HEX HEAD CAP SCREW $\frac{7}{16}$ " C 5 PL5-7/16CX5	HEX HEAD CAP SCREW $\frac{7}{16}$ " C 6 PL5-7/16CX6		
HEX HEAD CAP SCREW $\frac{1}{2}$ " C 2 1/2 PL5-1/2CX2 1/2	HEX HEAD CAP SCREW $\frac{1}{2}$ " C 3 PL5-1/2CX3	HEX HEAD CAP SCREW $\frac{1}{2}$ " C 3 1/2 PL5-1/2CX3 1/2	HEX HEAD CAP SCREW $\frac{1}{2}$ " C 4 PL5-1/2CX4	HEX HEAD CAP SCREW $\frac{1}{2}$ " C 4 1/2 PL5-1/2CX4 1/2	HEX HEAD CAP SCREW $\frac{1}{2}$ " C 5 PL5-1/2CX5	HEX HEAD CAP SCREW $\frac{1}{2}$ " C 5 1/2 PL5-1/2CX5 1/2	HEX HEAD CAP SCREW $\frac{1}{2}$ " C 6 PL5-1/2CX6

PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY



<p>HEX NUT</p> <p>$\frac{9}{16}C$ </p> <p>PL5-9/16C</p>	<p>LOCK WASHER</p> <p>$\frac{9}{16}$ </p> <p>LW-9/16P</p>	<p>FLAT WASHER</p> <p>$\frac{9}{16}$  SAE</p> <p>FW-9/16P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{9}{16}C$  $1\frac{1}{2}$</p> <p>PL5-9/16CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{9}{16}C$  2</p> <p>PL5-9/16CX2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{9}{16}C$  $2\frac{1}{2}$</p> <p>PL5-9/16CX21/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{9}{16}C$  3</p> <p>PL5-9/16CX3</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{9}{16}C$  $3\frac{1}{2}$</p> <p>PL5-9/16CX31/2</p>
<p>HEX NUT</p> <p>$\frac{5}{8}C$ </p> <p>PL5-5/8C</p>	<p>LOCK WASHER</p> <p>$\frac{5}{8}$ </p> <p>LW-5/8P</p>	<p>FLAT WASHER</p> <p>$\frac{5}{8}$  SAE</p> <p>FW-5/8P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{8}C$  $1\frac{1}{4}$</p> <p>PL5-5/8CX11/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{8}C$  $1\frac{1}{2}$</p> <p>PL5-5/8CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{8}C$  $1\frac{3}{4}$</p> <p>PL5-5/8CX13/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{8}C$  2</p> <p>PL5-5/8CX2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{5}{8}C$  $2\frac{1}{4}$</p> <p>PL5-5/8CX21/4</p>
<p>HEX NUT</p> <p>$\frac{3}{4}C$ </p> <p>PL5-3/4C</p>	<p>LOCK WASHER</p> <p>$\frac{3}{4}$ </p> <p>LW-3/4P</p>	<p>FLAT WASHER</p> <p>$\frac{3}{4}$  SAE</p> <p>FW-3/4P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{4}C$  $1\frac{1}{2}$</p> <p>PL5-3/4CX11/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{4}C$  $1\frac{3}{4}$</p> <p>PL5-3/4CX13/4</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{4}C$  2</p> <p>PL5-3/4CX2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{4}C$  $2\frac{1}{2}$</p> <p>PL5-3/4CX21/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{3}{4}C$  3</p> <p>PL5-3/4CX3</p>
<p>HEX NUT</p> <p>$\frac{7}{8}C$ </p> <p>PL5-7/8C</p>	<p>LOCK WASHER</p> <p>$\frac{7}{8}$ </p> <p>LW-7/8P</p>	<p>FLAT WASHER</p> <p>$\frac{7}{8}$  SAE</p> <p>FW-7/8P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{8}C$  2</p> <p>PL5-7/8CX2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{8}C$  $2\frac{1}{2}$</p> <p>PL5-7/8CX21/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{8}C$  3</p> <p>PL5-7/8CX3</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{8}C$  $3\frac{1}{2}$</p> <p>PL5-7/8CX31/2</p>	<p>HEX HEAD CAP SCREW</p> <p>$\frac{7}{8}C$  4</p> <p>PL5-7/8CX4</p>
<p>HEX NUT</p> <p>1C </p> <p>PL5-1C</p>	<p>LOCK WASHER</p> <p>1 </p> <p>LW-1P</p>	<p>FLAT WASHER</p> <p>1  SAE</p> <p>FW-1P-SAE-PC</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  2</p> <p>PL5-1CX2</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  $2\frac{1}{2}$</p> <p>PL5-1CX21/2</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  3</p> <p>PL5-1CX3</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  $3\frac{1}{2}$</p> <p>PL5-1CX31/2</p>	<p>HEX HEAD CAP SCREW</p> <p>1C  4</p> <p>PL5-1CX4</p>



HEX HEAD CAP SCREW $\frac{9}{16}$ " C 4  PL5-9/16CX4							
HEX HEAD CAP SCREW $\frac{5}{8}$ " C $2\frac{1}{2}$ "  PL5-5/8CX2 1/2	HEX HEAD CAP SCREW $\frac{5}{8}$ " C 3"  PL5-5/8CX3	HEX HEAD CAP SCREW $\frac{5}{8}$ " C $3\frac{1}{2}$ "  PL5-5/8CX3 1/2	HEX HEAD CAP SCREW $\frac{5}{8}$ " C 4"  PL5-5/8CX4	HEX HEAD CAP SCREW $\frac{5}{8}$ " C $4\frac{1}{2}$ "  PL5-5/8CX4 1/2	HEX HEAD CAP SCREW $\frac{5}{8}$ " C 5"  PL5-5/8CX5	HEX HEAD CAP SCREW $\frac{5}{8}$ " C $5\frac{1}{2}$ "  PL5-5/8CX5 1/2	HEX HEAD CAP SCREW $\frac{5}{8}$ " C 6"  PL5-5/8CX6
HEX HEAD CAP SCREW $\frac{3}{4}$ " C $3\frac{1}{2}$ "  PL5-3/4CX3 1/2	HEX HEAD CAP SCREW $\frac{3}{4}$ " C 4"  PL5-3/4CX4	HEX HEAD CAP SCREW $\frac{3}{4}$ " C $4\frac{1}{2}$ "  PL5-3/4CX4 1/2	HEX HEAD CAP SCREW $\frac{3}{4}$ " C 5"  PL5-3/4CX5	HEX HEAD CAP SCREW $\frac{3}{4}$ " C $5\frac{1}{2}$ "  PL5-3/4CX5 1/2	HEX HEAD CAP SCREW $\frac{3}{4}$ " C 6"  PL5-3/4CX6		
HEX HEAD CAP SCREW $\frac{7}{8}$ " C $4\frac{1}{2}$ "  PL5-7/8CX4 1/2	HEX HEAD CAP SCREW $\frac{7}{8}$ " C 5"  PL5-7/8CX5	HEX HEAD CAP SCREW $\frac{7}{8}$ " C $5\frac{1}{2}$ "  PL5-7/8CX5 1/2	HEX HEAD CAP SCREW $\frac{7}{8}$ " C 6"  PL5-7/8CX6				
HEX HEAD CAP SCREW 1" C $4\frac{1}{2}$ "  PL5-1CX4 1/2	HEX HEAD CAP SCREW 1" C 5"  PL5-1CX5	HEX HEAD CAP SCREW 1" C $5\frac{1}{2}$ "  PL5-1CX5 1/2	HEX HEAD CAP SCREW 1" C 6"  PL5-1CX6				

PRODUCT IMAGES NOT TO SCALE... SERVICED BY CUMBERLAND TRUCK/HARVEY'S SUPPLY